

Sent to Chief Surveyor

Received from Chief Surveyor

VESSEL'S NAME

of Indrasamha

Report

No.

For the ^{Ship} CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

These reports may be of interest to the Chief Ship Surveyor. The "Indrasamha" is a new steamer built under survey at Glasgow.

C. J. A.

11. 1. 02.

INDRASAMHA (s).—*Singapore, Jan. 10.*—Indrasamha (here follows a mutilated code word which may possibly mean—put back with sundry losses and damages sustained in heavy weather); 24 feet of water in the forehold, 6 feet of water in the mainhold. Cargo being got out as rapidly as possible.

INDRASAMHA (s).—*Singapore, Jan. 10, 10 50 a.m.*—Indrasamha put back with sundry losses and damages sustained in heavy weather, 24 feet of water in the forehold, six feet of water in the mainhold. Cargo being got out as rapidly as possible.—[The above is corrected version of telegram published in issue of yesterday.]

INDRASAMHA (s).—*Liverpool, Jan. 10, 3 12 p.m.*—Telegram received by owners dated Singapore, Jan. 9, states:—Indrasamha put back leaky; she leaks dangerously; No. 1 compartment full; 6 feet water in main hold. She encountered high and dangerous cross seas. The extent of damage is not yet ascertained.

INDRASAMHA (s).—*London, Jan. 11.*—The Salvage Association have received the following telegram from Lloyd's Agent at Singapore, dated Jan. 11, re Indrasamha:—Indrasamha will certainly have to discharge forehold. Hope need not discharge others. Damage below water not yet ascertainable.

*5197 tons 410.1 x 49.3 x 29.6 B.146. F.50 built by C Cornwell Res 10 mo '91
J. B. Roydon master*



© 2021

Lloyd's Register Foundation

W559-0179