

The 3rd S.S. No. 1 became due 4-35.

m. 10.33.

Rec'd
to Chief Surveyors 27. 5. 35

Received from Chief Surveyors _____

VESSEL'S NAME Sh. Se "MYRTIS" Report Liv. No. 105799

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - (Extract from Sub-Committee's Report, 24/5/32.)

Condition of Survey Condition When due _____

The vessel to be broken up on arrival at Mostyn (North Wales)
to which port she is proceeding.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

W.H.G. *[Signature]*
30.5.35

*Notes: Mr. 3/6/35
work of demolition will be reported
by the Surveyors*



© 2020

Lloyd's Register

Foundation W559-0003