

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stul. S.S. LIMNER*Rpt. *Bel*No. *8631*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *84.08*

Depth "d" —

Framing: Table No. —

Description

*Longitudinal framing*Longitudinal No. *34640*Proportions $\frac{\text{Length}}{\text{Depth}} =$

Upper Deck Sheerstrake and other scantlings as approved for vessels built in the Longitudinal System

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*100-A-1. (Stid) Carrying petroleum in bulk
2 Dks (Stid) & Webframes, Longitudinal framing
Cell D/Bu E.B 78' 2 1/2 t, D/Tf 32' 3 1/2 t, FPT 31 t, APT 13 1/2 t
FK, 16 BK (12 to upper Dk, 4 to 2nd Dk) pt Cur, Plyds A. CP.*

P109' B26' F46' Mchry Aff

In Del 28/10/21

*See letter
24/10-21*

M

TH

It is concluded the Cofferdams have been tested as required but the Surveyors should be requested to state if this is so.

25-10-21

© 2020

Lloyd's Register
Foundation

WS59-0286