

total capacity tons. F.P.T. COPY. feet tons.

Lloyd's Register of Shipping.



...the Surveyor has not made a special damage report H U L L. ...
Port ... they were damaged

3rd November, 1939.

REPAIRS, OR RE-EXAMINATION AS PER RULE, FOR ... of the vessel over a submerged object which struck ...

This is to Certify that I have
Surveyed the s.s. "LONDON TRADER", 646 tons gross of London,
whilst lying afloat in the Humber Dock, Hull, on account of the
alleged passing of the vessel over a submerged object which struck

heavily on port side in several places, before clear, whilst on
voyage from Middlesborough to Hull,
and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report, stating that all repairs
~~recommended by me have been completed to my satisfaction, and~~
~~that I have recommended~~ that she be continued as now classed
without fresh record of survey, subject to the vessel being dry

docked for further examination at the first convenient opportunity.

Frames	Have pumps	Flanking
Reverse Frames	Have bilge pumps	Gauging
Longitudinals	Have water	Transoms
Transoms	Have wash	Timbers
Floors	Have	Struts
Keelbolts	Have	Sails
Struts	Have	
Iron	Have	
Have	Have	
Have	Have	

General Observations, ...
...to remain
Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."