

(LLOYDS REGISTER.)

G. R. 130
Lloyds Register.

VESSELS OF 100 TONS AND UPWARDS.

These particulars are supplied by the Registrar General of Shipping and Seamen for the sole use of Lloyds Register of British and Foreign Shipping.

Signal Letters (if any) H.R. C.K.

Official Number.	Name of Ship.	No., Date, and Port of Registry.
129099	"Muritai"	49 in 1910 London.

No., Date, and Port of Previous Registry (if any) ✓

Whether British or Foreign Built.	Whether a Sailing or Steam Ship; and if a Steam Ship how propelled.	Where Built.	When Built.	Name and Address of Builders.
British	Steam Ship; Twin Screw	Belfast	1910	Workman Clark & Company Limited Belfast.

Number of Decks ...	Two Shelter	Length from fore part of stem, under the bowsprit, to the aft side of the head of the stern post ...	Feet.	Tenths.
Number of Masts ...	Two	Length at quarter of depth from top of weather deck at side amidships to bottom of keel ...	470	0
Rigged ...	Schooner	Main breadth to outside of plank ...	469	3
Stern ...	Round	Depth in hold from tonnage deck to ceiling at midships ...	58	2.5
Build ...	Clincher	Depth in hold from upper deck to ceiling at midships, in the case of three decks and upwards ...	31	7
Galleries ...	None	Depth from top of beam amidships to top of keel ...	-	-
Head ...	None	Depth from top of deck at side amidships to bottom of keel ...	35	6.3
Framework and description of vessel ...	Steel	Round of beam ...	34	6.2
Number of Bulkheads ...	Seven	Length of engine room if any ...	1	2.08
Number of water ballast tanks, and their capacity in tons ...	Nine 1430 tons		70	1

PARTICULARS OF DISPLACEMENT.

Total to quarter the depth from weather deck at side amidships to bottom of keel } 15300 Tons. Ditto per inch immersion at same depth } 55 Tons.

PARTICULARS OF PROPELLING ENGINES, &c. (if any).

No. of sets of Engines.	Description of Engines.	Whether British or Foreign made.	When made.	Name and address of makers.	Reciprocating Engines.		Rotary Engines.	N. H. P. I. H. P. Speed of Ship.
					No. and Diameter of Cylinders in each set.	Length of Stroke.		
Two	Vertical Inverted direct acting surface condensing triple expansion	Engines. British	Engines. 1910	Engines. Workman Clark & Company Limited Belfast	Three	22" 45"	✓	740 4000 12 1/2 Knots
No. of Shafts.	Particulars of Boilers.	Boilers.	Boilers.					
✓	Abnormal multitable	British	1910	Belfast	37"	62"		

PARTICULARS OF TONNAGE.

GROSS TONNAGE.		No of Tons.	DEDUCTIONS ALLOWED.		No. of Tons.
Under Tonnage Deck ...		6875. 19	On account of space required for propelling power		2329. 47
Space or spaces between Decks ...			On account of spaces occupied by Seamen or Apprentices, and appropriated to their use, and kept free from goods or stores of every kind, not being the personal property of the Crew		
Turret or Tank ...			These spaces are the following, viz.:-		
Forecastle ...		106. 81	Crew Officers' spaces in Forecastle		195. 99
Bridge space ...			Deck Houses		
Poop or Break ...		64. 74	Deductions under Section 79 of the Merchant Shipping Act, 1894, and Section 54 of the Merchant Shipping Act, 1906, as follows:-		
Side Houses ...		6. 59	Cubic Metres		
Deck Houses ...		219. 54	Made's Accommodation 12.35		108. 78
Chart House ...		4. 19	Boatswains Stores 62.14		
Spaces for machinery, and light, and air, under Section 78 (2) of the Merchant Shipping Act, 1894. ...			Chart House 4.19		
Excess of Hatchways ...		2. 53	Water Ballast Space 30.10		
Gross Tonnage ...		7279. 59	Total		2634. 24
Deductions, as per Contra ...		2634. 24			
Registered Tonnage ...		4645. 35			

NOTE.—The only spaces above the Upper Deck not included in the cubical contents forming the Ship's registered tonnage are:—

Bridge space from fore-castle bulkhead to tonnage opening	386 feet long	=	1432. 48 Tons
Space below tonnage opening	46 "	=	16. 65 "
Poop from tonnage opening to bulkhead	18.8 "	=	61. 32 "

Name of Master	John Charles Felgate	Certificate of Service Competency No.	21444
No. of Owners	The Tyser Line Limited, Head Office:- 16 Fenchurch Avenue in the City off London.		
Name, Residence, and Description of Managing Owner if there are more owners than one.	Walter Parkyns Tyser of same address. } Sixty four Shares		
Manage.	Walter Parkyns Tyser of same address.		
Dated	7th June 1910		