

17 FEB 1934

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Steel Sc. "STEFANIOS" Rpt. Bry No. 22458

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

The class is subject to 15 fathoms of chain cable being supplied.

The Barry Surveyors now report the vessel examined afloat and on account of wear and tear, 2 shell plates (slightly fractured) have been repaired and minor repairs carried out.


It is stated that 15 fathoms of chain cable have been placed on board and that arrangements have been made to produce certificate at first convenient opportunity.

It is submitted the vessel appears worthy to remain as classed without record of survey subject to 15 fathoms of chain cable being verified with certificate of test.

As now: subject etc.

Amend S.F.L.

WS62-0034



© 2019
Lloyd's Register
Foundation