

S.S. "MAGGIE O'REGAN".

This vessel is at present under survey at Hamburg.

Captain E. Murphy, the Master, has called at this Office stated that the large brackets which were intended to have fitted at the mid-length of each hatchway below the deck been fitted by the Repairers above the deck, thus obstructing the passage-way between the side coamings and the bulwarks.

Captain Murphy was shown the approved plans of the vessel which clearly indicate that these brackets are required to be fitted below the deck and not above.

It is submitted the Hamburg Surveyors be informed accordingly and that the approved plans of midship section profile be forwarded to them for their information and assistance in making the necessary alterations.

*2 plans to
Ham. 30/6/22.*

[Signature]
30.6.22.



© 2020

Lloyd's Register
Foundation