

F.E.

Received by Chief Ship Surveyor ^{4.9.06} ~~30.8.06~~

Received from Chief Ship Surveyor

VESSEL'S NAME *St. Steam Trawler "Sicyn"* Rpt. *Steel* No. *18287*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>10/16 in beam of 8/20</i>	<i>Not required.</i>
Spar Sheerstrake . .	<i>"</i>	<i>"</i>
Description of Framing:— <i>Ordinary increased to compensate (viz., ordinary, deep, zed, channel or bulb-angle) for omission of corner frames.</i>		

The hawsers are 1/2" and 1" respectively less in circumference than required by Table 22, but the owners have expressed their willingness to accept them, per letter attached.

In other respects This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed $\pm 100A1$ ("Steel") "Steam Trawler" as recommended.

$\pm 100A1$ ("Steel") "Steam Trawler"
1 DR.

BK 8" 4 BH Cem. Lloyd's A & C P 872.



C. H. P.
© 2020

Lloyd's Register
Foundation
W 563 0263