

Received from Chief Ship Surveyor **20 FEB 1934**

of Ship Surveyor

NAME Steel S.S. "HATKHOLA"

Rpt.

Form

No.

4792

**Notes of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

The Bombay Surveyor reports this vessel placed in dry dock, bottom cleaned and coated and the requirements of the 2nd S.S. No.1, due 1933, partly complied with.

It is submitted action be deferred.



© 2020  
19.2.34  
W566-0155

Lloyd's Register  
Foundation

London, 28th January, 1934.  
E.C.C.

30 FEB 1934

No. 1000  
Rpt.

The Chief Ship Surveyor are pleased to advise on this case for the consideration of the Insurance Commission.

RETAIN

The Chief Ship Surveyor are pleased to advise on this case for the consideration of the Insurance Commission.

1000  
1000-1000



© 2020

Lloyd's Register  
Foundation

of repairs, if any  
Account of Damage  
besides being detail  
ement of Anchors  
ack of this form. 5  
cases where t  
his services fo  
OR EXAM  
essel p  
could.  
OF DAMAGE REPA  
wed ... ..  
red and Faired or Re  
or Repaired in plac  
CONDITION OF TH  
Go  
Decks .....  
" ..  
sternings .....  
ing .....  
" ..  
mes  
la  
som Plating