

1

Sent to Chief Surveyors 18/11/09.

Received from Chief Surveyors

VESSEL'S NAME Stl. S.S.S. "Orvieto" Report Bel.No. Ltr.For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1<sup>st</sup> Entry.

When due

It is submitted that this 1<sup>st</sup> Entry Report be returned to the Belfast Surveyors and it should be pointed out to them that the shelter deck stringer angle is shown on report as being  $10\frac{1}{20}$  thick, and not  $15\frac{1}{20}$  thick as stated in their letter, and they should be requested to amend the report accordingly.

RM RM  
18/11/09

W567-0206



© 2021

Lloyd's Register  
Foundation