

20 JUL 1931

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Steel Sc.K. "RIGHTWAY"

Rpt.

Abn.

No. 16668

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Survey


The Aberdeen Surveyors report this vessel placed in dry dock after grounding and damage sustained to stem, keel, stern frame, rudder, shell plating, frames, floors, keelsons, bulkheads, etc.

The Surveyors state that the question of repairing the vessel is in abeyance as no agreement has yet been reached between the Owners and the Insurance Companies.

The Surveyors recommend that the classification should be suspended pending repairs.

It is submitted action be deferred for the present.

W564-0031



© 2020

Lloyd's Register
Foundation
16.7.31.