

Chief Ship Surveyor

Received from Chief Ship Surveyor

10 JUN 1931

NAME *M. Ty. Co. " ST. DAVID "*Rpt. *6ff*No. *49187*

Works of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Copy

e through collision & Cause not stated.

(See Liv Rpt. 97136)

repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
ed	10	4					
ed and faired	3						
repaired	4	2					
d or repaired							
place							

items:-

Vessel placed in dry dock, stem partly renewed & repaired & minor repairs effected.

Bottom coated.

submitted the vessel is worthy to remain as classed with,

rd of Survey 5,31 as recommended. Without special condition

A.I.

Shelter dk: with

freeboard

5,31 6ff.

Just Channel Service.

Without be

5.6.31



© 2020

Lloyd's Register
Foundation