

Less abo  
Engin  
TONNAG  
Less En

No.: SOUTHAMPTON 1128



# Lloyd's Register of Shipping.

20, Canute Road,

Southampton, 22nd September. 1922.

*Nobia*

LLOYD'S REGISTER.

LONDON  
23 SEP 1922

REC-  
LONDON

*5/10/22*

The secretary,  
LONDON.

Sir,

With reference to the First Entry Plans forwarded yesterday on S.S. "MUREX", we beg to inform you that the fees for same have not been rendered as it is understood that these will be sent direct to the Admiralty from London.

The anchor Certificates for 2 Bowers have not been produced as yet and the steel Tow Wire placed on board is  $4\frac{1}{2}$ " instead of 5" and the Dockyard have been informed that this requires changing.

The first entry report on Electric Lighting has not been returned as yet from the Dockyard but will be forwarded as soon as returned.

We are, Dear Sir,

Yours faithfully,

pro The Surveyors



*G. A. Dryden Tozner*

Lloyd's Register  
Foundation

*W564-0171*



Referred to the Chief Ship Surveyor,  
and the Chief Engineer Surveyor.

23 SEP 1922

Referred to Mr. Mayne.

© 2020

Lloyd's Register  
Foundation



Engine Room  
TONNAGE FOR  
Less Engine  
Less Navigational

Register Tonnage  
as entered on B  
LENGTH  
as per B

Dimensions

FRAME,

Do. in p  
Do. in w

Spacing of

REVERS

Do. in w

FRAMING  
FLOORS

Do. in w

Do. in w

FLOORS

Do. in w

Do. in w

Do. in w

Do. in w

Do. in w

Do. in w