

REPORT OF SURVEY for REPAIRS, &c.

WR
SECTION

R SECTION No 17

WRECK
BOOK

10442

REPORT OF TOTAL LOSS, CASUALTY, &c.

PETTEN

No. 60607 in R. B.

Wreck Book, p. 173/40

EX

Date of writing this report

19

Vessel's Name *Saet Steam Trawler "Lord Incheape"* of *Hull* Tons {Gross 338

Net 137

Built at *Hull* When *1924* *12* Casualty notice sent to Owner ☒ Owner's reply ☒Owner's Name *Kellyer Bros. Ltd.,*Address *St. Andrew's Dock, Hull.*Case previously before
Classing Committee.

Date

Last Minute

Particulars of Classification.

+ 100 A1.	+ LMC 536
stm. Trawler	BS 938
639	
S.S. Hul. N ^o 3536	T.S. N 738CL

Date of Casualty *December Quarter*Précis of particulars of Casualty *The Admiralty announced on the 2nd*

November, that this vessel had been sunk by enemy
mine.

SOURCE OF INFORMATION.

CL 4/11

TWO H.M. TRAWLERS SUNK

The Board of Admiralty regrets to announce that H.M. trawlers *Hickory* (Lieut. R. E. Hardinge, R.N.V.R.) and *Lord Incheape* (Temp. Skipper O. B. Bell, R.N.R.) have been sunk by enemy mines. The next of kin of casualties have been informed.

LL 4/11

DISCLOSED
SECTIONWRECK
SECTION

No. _____

R SECTION No 17

Suggested Record ☒

Date of Committee

OMITTED FROM R.B.
TUE. 24 DEC 1940

Committee's Minute

OMITTED FROM R.B.



© 2019

Lloyd's Register
Foundation

W57-0007

W57-0012