

SUNDERLAND N^o 31217Port of SunderlandMay 8th 1933

REPORT ON MASTS, SPARS, AND RIGGING.

Sir

Having, in accordance with your instructions,

examined the Masts, Spars, Iron Work of same, and Rigging, of the

of Vessel)

SS Llanarth lying at Dickinsons Quay(Date of examination) May 8th 1933,

I have to report that I found

Main Topmast decayed on
 Port Fore bant, Recommend that decayed
 be cleaned out, and Topmast repaired
 boxes of Fore and Main Rigging Screws
 and Main Topmast Backstay Screws
 stay and Fore Topmast Stay, Weak
 Strained at the Holes, Recommend
 crews be eased up, and Boxes annealed
 examination, and renewed where required
 sts, Rigging, other spars and Ironwork
 in good condition

H. D. Pearson

Surveyors,

and's Register of Shipping,

Sunderland

© 2019

Lloyd's Register
Foundation

W5T-0105

with Fresh Record of Survey 5.33 and the Mel...