

1m, 10.39.

3 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "LLANFAIR".

Rpt.

Npt.

No.

24257.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey SPECIAL SURVEY OF ~~ENGINES AND/OR~~ BOILERS PARTLY HELD ~~FOR S.S. No.~~

~~LMC~~~~LMC(M)~~~~MS~~

BS

due 9,39 , partly held

~~now further advanced~~ and the following repairs effected (due to wear & tear

Some stays renewed in the donkey boiler.

Screw shaft examined.

It is proposed to complete the survey on return.

It is submitted that this proposal merits approval and the vessel is eligible to remain as classed, and WILL BE eligible for the record BS2,40 when the survey has been completed, & S2,40 now.

The following remains to be done to complete the Survey

Adjust donkey boiler safety valves.



© 2019

Lloyd's Register
Foundation

4.3.40.

W57-0193

to be shown as classed with Records of Tail Shaft Seen