


Submitted Messrs. Wilson & Gilman
should be requested when forwarding their
report to forward a sketch of the fore part
of the vessel giving in detail particulars
of all the damage found and showing the
position of the stringers beams &c & this
part and the position & form of the fractures
in the shell plating.

18/1/13
20/1/13

E. B. L.
18. 1. 13
C. B.
© 2020



W 570 0040
Bloy's Register
Foundation