

s.s. "LUMINA"

The class is subject to the sternframe, repaired by electric welding in 3.31 being specially examined at the next dry docking.

The 2nd No.1 became due in December, 1933.


The ship being laid up, the Owners have furnished the usual undertaking.

The Newcastle Surveyors now report the vessel examined afloat and a satisfactory general examination carried out with a view to enable the vessel to proceed to a U.K. or Continental port in ballast for breaking up purposes.

The vessel is now at Blyth, the work of demolition having commenced.

It is submitted no further action is necessary.

13.6.35.



© 2020

Lloyd's Register
Foundation
W 510 0226