

COPY.

Lloyd's Register of Shipping.



Port SOUTHAMPTON.

10th May, 1938.

This is to Certify that

Wm. COWIE.

the undersigned Surveyor to this Society did at the request of the Owners' representative attend on board the Q.S.S. "BERENGARIA" of Liverpool, 52101 tons gross register, whilst lying in the Ocean Dock, Southampton, on the 14th March 1938 and subsequently, for the purpose of ascertaining and reporting upon the nature and extent of damage stated to have been caused by Fire whilst the vessel was lying at New York on the 3rd March, 1938. For further particulars please see log books.

Upon examination the undersigned:-

FOUND:-

Games Deck over Main Lounge
Starboard side, wood deck
burnt,

5 steel deck plates distorted
and buckled.

4 deck beams distorted and
buckled.

RECOMMENDED:-

To renew.

4 to be renewed and one to
be faired.

2 to be renewed and 2 to be
faired.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

COPY.

-2-

10th May, 1938.

"BERENGARIA".

FOUND:-

No.1 Expansion joint

leathers on Games Deck

and Boat Deck, burnt

(Starboard side).

Fore and aft girder buckled

(Starboard side).

52 glasses over outer Lounge

Dome cracked.

3 glasses in Lounge Deck

House, cracked.

2 lengths of 100 feet

each of canvas fire hose,

scorched and damaged.

2 Fire axes lost.

RECOMMENDED:-

To renew.

To be faired.

To renew.

-do-

-do-

-do-

In addition to the above the furniture, panelling, furnishings electric wiring and fittings of the Lounge and its approaches were damaged by fire, smoke and water.

The whole of the work to be carried out in an efficient and workmanlike manner together with all incidental removals and replacements, new and disturbed work to be coated with approved covering, so as to place the vessel and her equipment in the same condition as before the casualty.

FEE:- £5. 5. 0.

Handwritten signature

SURVEYOR TO LLOYD'S REGISTER
OF SHIPPING.



© 2020

Lloyd's Register
Foundation

W572-002672