

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose or not.
declined? ☒ Was a damage report made by anyone else? If so, by whom?

TELEGRAMS: REGISTER LIVERPOOL.

TELEPHONE: CENTRAL 5282 & 6664.



Lloyd's Register of Shipping.

201, Tower Building,

Liverpool, 27th February 1918.

RECEIVED
LONDON.

REC'D FEB 28 1918

2. Enclosures.

H.

Dear Sir,

With reference to your letter of the 23rd instant respecting the screw shaft of the S.S. "MANX ISLES" I am informed by Mr Barrett that the Superintendent had mentioned the matter of extending the limit to him but he had received no communication regarding the case.

I have therefore seen the Superintendent, and transmit herewith a letter since received from him, also one from Mr Barrett.

I am, Dear Sir,

Yours faithfully.

W. J. Selous
Secretary to the
Liverpool Committee.

A. Scott, Esq.,

LONDON.E.C.



© 2021

Lloyd's Register
Foundation

Repair Fee (if any) £ 2 2
Expenses (if chargeable) £

Received by me,

2-3-1918

6-3-18

Engineer Surveyor to Lloyd's

act of holes causing under the main. Also a 1/4" pipe between the cross

Ch

When

Number of Ridgese.	Ant
1st B	
2nd	
3rd	
Coast	
Shore	
Kelg	

Number of
Certificate.

on Stream Chain }
or Steel Wire... }

Referred to the Chief Engineer Surveyors

7th Mo

FEB 28 '88

Also for Mr S. A. Hill to note

S.A.
2-2-18.



© 2021

Lloyd's Register
Foundation

Messrs

Dear S

regard

to Adm

at Grif

for in

"Inver

glad i

time t

Henry
William
Joseph
44
33
69