

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 24<sup>th</sup> Oct 1933 When Mended in at Local Office 25<sup>th</sup> Oct 1933 Port of Falmouth  
 No. in Survey held at Falmouth Date, First Survey and Last Survey 24<sup>th</sup> Oct 1933  
 Reg. Book. 32590 on the Wood, Iron or Steel S.S. Pakipaki (No. of Visits 1)

TONNAGE:— Built at Hensburg By whom Hensburgs Schiffsb. Ges. When 1914 YEAR. MONTH.  
 GROSS 7166 Owners Federal Steu. Nav. Co. Ltd. Owners' Address (if not already recorded in Appendix to Register Book).  
 UNDER DEK. 6612 Managers ✓ Port belonging to London  
 NET 4516

Surveyed Afloat or in Dry Dock? Yes Name of Dock Mylor Pool River Fal Destined Voyage Fal  
 WB=CellDBorDBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted  
 total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements

N.B.—All alterations in the existing records should be underlined.  
 If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 7991 Port Fal

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

On damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined H. 18/10/33 + 23/10/33

Society's Freeboard (if assigned) as painted on Ship and now verified ✓ ft. ✓ ins.

Interim certificate attached Was a damage report made by anyone else? If so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR General Examination.

Now done:— The following examination was carried out whilst vessel was lying afloat at Mylor Pool, River Fal—  
 Holds, tween decks, peaks, machinery space, tunnel, bunkers (as far as practicable), weather decks, casings, hatchways, webs, hatches, tarpaulins and battening arrangements, windlass & steering gear examined.  
 The vessel is in a fit condition for the contemplated voyage, having been disposed of for breaking up in Italy—  
 The proposal for the vessel to load a non-perishable cargo & proceed from the United Kingdom for breaking up in Italy in my opinion merits the approval of the Committee

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks <u>good</u>	✓	✓	(State if on Bolt). ✓
Walking of Decks <u>✓</u>	State if Tanks now tested <u>✓</u>	Dblng. Plates under Sounding Pipes <u>✓</u>	When put on, Month <u>✓</u> Year <u>✓</u>
Casings <u>see Rpt. good</u>	Bulkheads <u>see Rpt. good</u>	Engine Room Skylights <u>good</u>	Boats <u>good</u>
Beams & Fastenings <u>see Rpt. good</u>	Ceiling <u>✓</u>	Coal Bunkers, Open'gs, Lids, &c. <u>see Rpt.</u>	Masts, Yards, &c. <u>✓</u>
Outside Plating <u>✓</u>	Cement or Asphalt (State which.) <u>✓</u>	Oil Bunkers <u>✓</u>	Condition, how ascertained <u>from deck</u>
" " in way of sidelights <u>good</u>	Rudder <u>✓</u>	Scuppers <u>good</u>	(State if wedges removed) <u>✓</u>
Reasthooks <u>see Rpt. ✓</u>	Steering gear and its connections <u>good</u>	Cargo Hatchways <u>✓</u>	Sails <u>✓</u>
Ransoms <u>✓</u>	Windlass <u>✓</u>	Hatches <u>✓</u>	Equipment letter <u>d +</u>
Frames <u>see Rpt. good</u>	Have Pumps now been examined and found efficient? <u>✓</u>	Planking <u>✓</u> of Wood Vessels <u>✓</u>	Anchors, No. of <u>3 B. 15.</u>
Reverse Frames <u>✓</u>	Have Sluice Valves now been examined and found efficient? <u>✓</u>	Caulking <u>✓</u> ditto <u>✓</u>	Cables (State if now ranged) <u>no</u>
Longitudinals <u>✓</u>	Have Watertight Doors now been examined and found efficient? <u>✓</u>	Trenails <u>✓</u> ditto <u>✓</u>	" length <u>✓</u> (on board) <u>✓</u> diam. <u>✓</u>
Transverses <u>✓</u>	Have Ventilators and their Coamings been examined and found efficient? <u>✓</u>	Breasthooks & Stems <u>✓</u> ditto <u>✓</u>	" Rule length <u>✓</u> size <u>✓</u>
Floors <u>✓</u>		Transoms, Pointers, & Crutches <u>✓</u> ditto <u>✓</u>	Hawser & Warps <u>✓</u>
Keelsons <u>✓</u>		Timbers of Frame at openings <u>✓</u> ditto <u>✓</u>	Standing and Running Rigging <u>good.</u>
Stringers <u>good</u>		Ditto Ditto at other places <u>✓</u> ditto <u>✓</u>	
Inner Bottom Plating <u>✓</u>		Stringers, Clamps & Shells <u>✓</u> ditto <u>✓</u>	
		Salting <u>✓</u> (State if examined.) <u>✓</u>	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptnd24, &c."

This vessel as far as now seen is eligible in my opinion to remain as classed without fresh record of survey having been found in a satisfactory condition to load a non-perishable cargo, to proceed from the United Kingdom for breaking up in Italy

Survey Fee (per Section 20) £ : : Fees applied for, 25<sup>th</sup> Oct 1933  
 Special Damage or Repair Fee (if any) £ 5 : 0 : 0 Received by me. Arthur Sculthard  
 Travelling Expenses (if chargeable) £ : : 11 19 33  
 Second Surveyor's Fee (if any) £ : : ✓

Committee's Minute Deferred

Character Assigned Deferred

FRI. 10 NOV 1933

FRI. 2 FEB 1934

Surveyor to Lloyd's Register of Shipping

Lloyd's Register of Shipping  
 Foundation

WS76-068