

116 DEC 1933

by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

SHIP'S NAME Steel Sc. "CULMORE"

Sou 15256
Hul Rpt. No. 44269

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey _____

The Southampton Surveyors report this vessel examined afloat, the requirements of the 1st S.S. No.3, due 7,33, partly complied with and minor repairs effected.


The Hull Surveyors report the vessel placed in dry dock, the Special Survey completed and the bottom cleaned and coated.

It is submitted the vessel appears worthy to remain as classed with record of survey 12,33 Hul and notation of S.S. Sou No.3-11,33.

100A1
12,33 Hul
S.S. Sou No.3-11,33

It is concluded it was not considered necessary to drill the shell plating, but the Hull and Southampton Surveyors should be requested to state if this is so.

WS 80 - 0016



Lloyd's Register
Foundation