

IMPERIAL AND INTERNATIONAL COMMUNICATIONS LIMITED



Clerk's Name.

Time Received.

WLA 224 DURBAN 48 1 LF =

WLT COMMITTEE LN =

ARE

MUNTERS REPAIRS RECOMMENDED AND BEING
EFFECTED TO MAKE VESSEL FIT FOR FULL DRY
AND PERISHABLE CARGO STOP BRIDGE HOUSE
FRONT RENEWED STOP COLLISION BULKHEAD
DEFECTIVE PLATING RENEWED STOP ENGINE ROOM
BULKHEAD DEFECTIVE RIVETTING
RENEWED STOP DEFECTIVE DECK PLATING

NO ENQUIRY RESPECTING THIS TELEGRAM CAN BE ATTENDED TO WITHOUT PRODUCTION OF THIS COPY.
REPLIES SHOULD BE HANDED IN AT ONE OF THE COMPANY'S OFFICES.

© 2021

Lloyd's Register Foundation

CONTINUATION SHEET No. 2

I. AND I. C. Ld.

Name

Committee

Circuit Ref.

Wla 226

RENEWED STOP DEEP TANK BULKHEAD REPAIRED

STOP



© 2021

Lloyd's Register
Foundation

W 582 0232 72

Referred to the Chief ~~Ship~~ Surgeon.

as

L3 NOV 1930

Also for Mr. S. A. Hill to note.

Also for Mr. Carey to note.

Shel
MS



© 2021

Lloyd's Register
Foundation