

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

Enclosure.

8th August, 1930.

Dear Sirs,

S. Reverting to my letter of yesterday's date respecting the Steamer "HUNTRESS, I have to inform you that I am now in receipt of a cablegram from the Society's Surveyor at Durban, reading as follows, viz:-

HUNTRESS IN VIEW OF DETERIORATION FOUND GENERALLY UPPER DECK TWEEN DECKS COLLISION BULKHEADS DEEP TANK BULKHEADS TANK TOP AND INTERNAL SURFACES OF SHELL CONSIDER VESSEL IS UNSATISFACTORY FOR DRY AND PERISHABLE CARGO OR FULL DEADWRIGHT SOUTH AFRICAN GOVERNMENT SURVEYORS CONCUR.

I enclose herewith an account for the cost of the cablegrams sent in this case.

I am, Dear Sirs,

Yours faithfully,

Secretary.

Messrs. Vergottis, Ltd.,
Billiter Buildings,
Billiter Street,
E.C.3.



© 2021

Lloyd's Register
Foundation

W582-0268

Conferring cables
sent 7/8 rec'd 8/8
to Durban (P. H. H.)

11, Rensselaer Street, N.Y.C. 3.

Group of 10

Y900



© 2021

Lloyd's Register
Foundation