





Damage - Cause not stated.

Some coupling bolts  
removed & a propeller blade

re-fastened.  
H. 2 line 7. 28. To be held in May or June  
left?

It is submitted that  
this vessel is eligible to  
remain as GLASSED.

B. A.  
28/3/29

N.B. - If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register  
Foundation