

Do. of A  
Do. of ea  
Do. above  
Enain

F.E.

Received by Chief Surveyor 7. 10. 01

Received from Chief Surveyor \_\_\_\_\_

VESSEL'S NAME Ste. S. S. "Rijndam" Report Bel. No. 5326

The remarks of the Chief Surveyor are desired on this Case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . . .	<i>as approved</i>	
Spar Sheerstrake . . .	<i>✓</i>	<i>✓</i>
Description of Framing:— <i>Channel, as approved.</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed † 100 A 1 ("Steel") "Auring Deck with freeboard," as recommended. The Summer freeboard of  $15'' 7\frac{1}{2}$  from centre of disc to top of statutory deck line at *Auring* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

† 100 A 1 ("Steel") Auring DR. with freeboard  
 3 DR (Ste - UWS) & Auring dk. (see - WS)  
 W.B = Cell DB a 151' m EYB 107' f 191' 1847E DTf 56' 1620E FPT 147E APT 75E  
 FK & BK 3" 10 BH Cem. Lloyd's A & CP Promenade Dr 193'



© 2021

Lloyd's Register  
Foundation

W583-0008

PH

WEB-FR