

Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs

6-19.
S.S. Form No 3, 9-14

BY BROS. & Co

TELEPHONE 495 CENTRAL (4 LINES).
TELEGRAPHIC ADDRESS:-"PATROL," LIVERPOOL.
CODES:-A.B.C. 5TH EDITION. SCOTTS 10TH EDITION.

FRANK BIBBY.
ARTHUR W. BIBBY.
HERBERT K. BIBBY.
A. HAROLD BIBBY, D.S.O.
G. W. ROBINS.

LLOYD'S REGISTER
LONDON
REC'D 20 FEB 1920
ANSI
ad 1/32 h
ENCLOSURE

IN THE EVENT OF THE STEAMER OR STEAMERS BEING REQUISITIONED FOR GOVERNMENT SERVICE ANY CONTRACT OF CARRIAGE TO BE NULL AND VOID AND NO LIABILITY TO ATTACH TO SHIPOWNERS FOR ANY CONSEQUENCES ARISING THEREFROM.

26 CHAPEL STREET,

LIVERPOOL, 26th Februry. 19 20.

BIBBY LINE
FOR
EGYPT, COLOMBO, TUTICORIN,
TTAGONG, BURMESE PORTS, &c.

The Secretary
~~Stevens Esq.,~~

Engineer Surveyor,
Lloyd's Register of Shipping,
Fenchurch Street,
London.

Dear Sir,

S/S "WARWICKSHIRE"

DAMAGED L.P. CRANK SHAFT

We shall be glad to have at your convenience, a copy of the report of your Survey and recommendation for the renewal of the above.

We understand from our Superintendent Engineer, Mr. Hall, that you already have extracts from the Log Book referring to the damage in the Suez Canal. If not, we will send copies on to you.

Yours faithfully,

[Handwritten Signature]



© 2020

Lloyd's Register
Foundation

W584-0136

Installation 5 5 0 | 26 FEB 1920

Referred to the Chief Engineer Surveyor

H M.

28 FEB 1922

Referred to Mr. G. A. G.

Submitted The London
Surveyor should be out
a damage report to make they are
in a position to do so
F. R. G.

THE LONDON SURVEYOR

2/28

London.
The London Surveyor
is referred to the Chief Engineer
Surveyor.



© 2020
Lloyd's Register
Foundation

Rep
cases
are dec
OR
State clea
survey, thr
y, 1, 1, 5, " or
al On
Rep Section
age on Repa
20. 1