

28. 2. 36

of Surveyors 26. 2. 36

Received from Chief Surveyors

NAME 2 - Baltoria

Report Am

No. 1018291

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

3rd No. 2 SURVEY PARTLY HELD.

2.35 When proposed to be completed

Survey held, &c. Partly held on machinery

The 3rd S.S.No.2 became due 2,35 and a proposal to carry out same within the year of grace has been agreed to.

Permanent repairs require to be effected to stem and stem plating and margin on port side of No.6 double bottom tank at the Special Survey.

A request by the Owners for an extension of the vessel's present classification to allow her to operate from the middle of June next to the middle of September (the ship to be laid up from February to June) received consideration on the 17th January last when the Owners were informed that the Committee could not agree to the extension desired in view of the fact that the vessel will be 34 years old in April next and that the year of grace will expire at the end of this month. The Owners were further informed that as it would appear that the vessel was to be laid off her present service at the end of this month until June next the Committee considered that this would present a favourable opportunity of carrying out the overdue Survey.

© 2020 Lloyd's Register Foundation
WS85-0017 1/2 P.T.O.



"BALTONIA"

-2-

In reply to enquiry the Owners state that no further arrangements in regard to the outstanding matters of survey have been made as the vessel is laid up.

The year of grace will expire at the end of the present month.

It is submitted action be deferred and the Owners asked to furnish the usual undertaking.

 
27.2.36 



© 2020

Lloyd's Register
Foundation

WS85-00172