

25 JAN 1930

Inspected by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel S.S. "PAOLINA GIUFFRIDA" Rpt. Tri No. 8657

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/29.)


Course of Survey _____

The S.S. No.2, due 5,27, has been partly held and to complete same the wood after and poop decks and hatch carrier angles require to be repaired.

The Trieste Surveyors now report that repairs have been effected to the wood after and poop decks and the hatch carrier angles

It is submitted the vessel appears worthy to remain as classed with record of survey 12,28 and notation of S.S. No.2-28.

100A1
Spar dk.
12,28 Msl.
S.S. Msl No.2-28



Wanna
23.1.30.



© 2020

Lloyd's Register
Foundation
W585-0361