

Steel S.S. "San Eduardo"

The fitting of the furnace fronts as  
now fitted obviates the necessity  
of drip trays under the furnaces.

ARRR

20.1.13



© 2020

Lloyd's Register  
Foundation

W 589-0091