

COPY.

23rd August, 1921.

Extract from New York letter dated 10th instant.

s.s. "SWIFTEAGLE"

"With reference to the enquiry contained in your semi-official letter of the 30th June - I am forwarding herewith a letter received from Mr. Lang regarding the various scantlings referred to."

"SWIFTEAGLE" Report No. 232
Reference to your letter of July 1921
The floors in the Boiler Space were
fitted as specified, namely, .53", and the Stagnal Shells
Deck Side Stagnal-plates and "H" Bar longitudinally "crossed"
40 lbs. and 40 lbs. weight per foot respectively and .40"
.40" and .40" as stated. The scantlings of the Lower
Transverse of the Side were fitted as approved.
To regret that these errors were made.

Very very truly,
Wm. Lang



© 2020

Lloyd's Register
Foundation

Ws89-0203

Ws89-0204

