

1m.12.15.

F.E.

Received by Chief Ship Surveyor 27-8-14

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "War Soldier"

Rpt. Kob.

No. 2045.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 92.

Depth "d" 19.92

Framing: Table No. 3 page 16.

Description C equivalent to C as approved

Longitudinal No. 40940

Proportions $\frac{\text{Length}}{\text{Depth}} = 10.6$

Bridge Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed * 100 A.1. (steel) as recommended.

2 DKS. (steel)

CELL. DB. 375', 1192 t., DT. a 42', 1312 t., F.P.T. 55.2 t., A.P.T. 60.2 t.

F.K., T.B.H., Cem., Lloyd's a & C.P., P. 34', B. 138', F. 37.



© 2021

Lloyd's Register Foundation

W590-0135

Bulb Angle, Plate, Tee Bulb or Channel
Angles on upper edge A. 7 8 3 46

Tie Plates
Deck. Material and thickness

Steel on