

6, 31, 11, 10, 10, 9

n.7.31.

24 MAR 1932

ived by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Twin Sc. "FERNDALE" Rpt. Lon. No. 97324

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

ure of Survey

The London Surveyors report this vessel placed in dry dock and some bottom plates etc. at aft end on port side, found indented, (cause not stated) have been temporarily dealt with to their satisfaction.

The Surveyors recommend permanent repairs be effected at the first convenient opportunity.

It is submitted the vessel appears worthy to remain as classed with record of survey 3.32, subject as recommended.

100A1 ) subject etc.
Shelter deck with freeboard )
3.32 Lon. )
Fitted for oil fuel etc. )

WS41-0117



© 2020

Lloyd's Register Foundation

23.2.32

Table with 4 columns: Longitudinals, Transverses, Have Sluice Valves now been examined and found, Breasthooks & Stemson, Transoms, Pointers, & Crutches ditto, Anchors, No. of, Cables (State if no...