

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. Sc. Sr. "SUNTEMPLE"

Rpt. Scu. No. 11705

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

This vessel has been under survey for ~~re~~classification at Southampton and the Surveyors report the vessel has been placed in dry dock and the requirements for vessels not built under survey partly carried out.

It was not considered necessary to drill the shell plating.

The vessel is now under survey in London.

It is submitted no action is necessary, but the London Surveyors should be informed of the items required to complete the survey.

To complete the survey see report.

It would appear that in addition to the items mentioned in the report as required to complete the survey the holds and tween decks require to be examined, the ceiling lifted, and plating in way of side lights to be examined, but the Surveyors should be requested to state if this is so.



© 2021

Lloyd's Register
Foundation

W592-0099