

Do. above Crown of
Engine Room ...

87.64
1221.02

Longitudinal Number

13500.0

By whom built. *Aulsa S. S.*
Owners *General Stm.*

1

Sent to Chief Surveyors

21. 10. 14

Received from Chief Surveyors

VESSEL'S NAME

MS. S. Raven

Report

No. 34479

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

When due

*100 A.1 (Steel) Shelter deck with freeboard
1 SH (SH) and Shelter deck (p^c SH. W.S.)
WB bell DBf 163' 26" t. FPT 20t. APT 20t.
SH 4 RH. "Cm." Lays at 6 P. "Mozy Aft."*

*M. W. W. 14
21. 10.*



© 2020

Lloyd's Register
W593-0121
Foundation

Angles on upper edge
Spacing
BEAMS, Poop Deck, Angle, Bulb Angle, Plate,
Tee Bulb or Channel

Angles on ditto
Tie Plates