

total capacity / tons. FPT tons; APT tons; MT feet tons.
N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing.

CHARACTER.
* for Special Survey.
Date of last Survey and of Periodical Surveys.

POSTPONED SURVEYS.

Case of the Steel S.S. "HIGHLAND WATCH".

72163 in Reg. Bk. 6031/3863 tons, Built 1904-3 mo.

sed +100 A1 Owners H. & W. Nelson, hd mngrs.
ter Bk with freeboard

11,26 + LMC 7512,23 Port of Registry London.
N03-3,16 MS 12,23 C.L.
N02-25 Bd 12,25
Lloyd's Rmc 12,26

ey due Screwshaft Survey due December, 1926.
Boiler Survey due December, 1926.

In January last the Owners stated the vessel had just sailed but that on her return they would have the above surveys attended to.

The Newcastle Surveyors now write that the vessel is at present laid up indefinitely in the Tyne and that the Boiler Survey is proceeding. They add, however, that no definite arrangements have yet been made as regards drydocking the vessel for the inspection of the screwshaft.

Submitted action be deferred.

J.L.
16-5-27

TUES. 17 MAY 1927

Committee's Minute

Decision

Deferred

MH



© 2020

Lloyd's Register
Foundation

S.S. SHL. 2nd N03. 11-27 being deferred until the Survey is complete