

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Date of last Survey and of Periodical Surveys.
+ 100 A1 Shutey 20
11-26
1-16
15



Lloyd's Register of Shipping,

71, Fenchurch Street,

London, 11th May, 1927.

E.C.3.

H.

To the Surveyors at

NEWCASTLE-ON-TYNE.

Vessel's Name,

S.S. "HIGHLAND WATCH".

QUESTION.	ANSWER.
<p>With reference to your report N^o80710, it is observed from the shipping papers that this vessel arrived in the Tyne on the 11th ultimo, and I shall be glad to learn what action has been taken on this occasion regarding the Boiler and Screw Shaft Surveys which became due at the end of December last.</p>	<p>Date:— 12th. May 1927. This vessel is at present laid up indefinitely in the Tyne, and the boiler survey is proceeding. No definite arrangements, however, have yet been made as regards dry docking and inspection of the tail shaft.</p>
	<p>THE SURVEYORS, per </p>



© 2020

Lloyd's Register Foundation

S.S. Shl. 2nd no 3. 11-27 being deferred until the Survey is complete

assigned)
how verifi
Newzi
age
Marl
skirk
Palu
def
dock
deck
tailed
or Y.M. of V
te if on Fe
put on, Mo
ards, &c...
n, how ascer
e if wedged
nt letter ...
No. of ...
state if now
gth 270
on board
le length...
& Warps ...
and Runnin
Register B
s classed a
le in
the

Ink
in the space