

S.S. "HIGHLAND WATCH". Report No.13871.  
---oo0oo---

The following holds and tween decks are insulated with charcoal for cargo purposes.

|                         |     |     |     |     |     | <u>Cubic ft.</u> |
|-------------------------|-----|-----|-----|-----|-----|------------------|
| Fore hold               | ... | ... | ... | ... | ... | 48395            |
| Main hold               | ... | ... | ... | ... | ... | 56355            |
| After main hold         | ... | ... | ... | ... | ... | 46830            |
| After hold              | ... | ... | ... | ... | ... | 25290            |
| Fore tween decks        | ... | ... | ... | ... | ... | 14255            |
| Main " "                | ... | ... | ... | ... | ... | 22630            |
| After main tween decks. | ... | ... | ... | ... | ... | 10625            |
| After tween decks       | ... | ... | ... | ... | ... | <u>14745</u>     |
| Total.                  |     |     |     |     |     | <u>239125</u>    |

The refrigerating machinery for cargo purposes has been supplied and fitted in after and main tween decks by Messrs. Haslam Foundry and Eng. Co. Lim., "Duplex Triple Expansion Machine". "Ammonia System". "Brine Pipes".

*J. French*  
6.4.04.



© 2020

Lloyd's Register  
Foundation

W5915-0202

Tie Plates .....  
Deck. Material and thickness STEEL  
Deck Stringer Plate, b'dth & th'kns