

ved by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME Steel Twin Sc. "HEREFORDSHIRE"

Rpt. Bry.

No. 22083

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92).

re of Survey

The class is subject to 15 fathoms of chain cable being supplied.

The Barry Surveyors now report that fifteen fathoms of chain cable have been placed on board and verified with the certificate of test.

It is submitted the vessel appears worthy to remain as classed without record of survey and without special condition.

as now, without etc.



© 2020

Lloyd's Register
Foundation

W595-0024

29.10.32

COPIES

© 2020

Lloyd's Register
Foundation



Last
by the
the tanks
grinders, and

percentage of
expense of the
on account
and residue
replacement
the back of

in damage c
offered h

REPAIRS,

How

NO. 55034

218 10H

218 10H

218 10H

218 10H

218 10H

Assignment of rights and interests in the property of the company

SUMMARY OF
Removed
Removed a
Fitted or

PRESENT COND

Decks

Caulking of Decks

Coatings

Beams & Fastenings

Outside Plating

Breasthooks

Trunnions

Frames

Levee Frames

Longitudinals

Transverses

Loose

Sealants

Welders

Upper Bottom Plating

General

State

this survey

survey, 24

son

son

son

son

son

son

son