

Chief Surveyors

Received from Chief Surveyors

SHIP'S NAME *St. Se. "SAINT SIMON"*

Report *Sw.* No. *102978*

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey

First Entry

When due

100 A. 1 (Steel) "Steam Trawler"


10k

BK. 7 1/2", 3BH, Cam

D. 72', F. 21'

no of description on the back of their reports regarding the deck, the Surveyors
 should be requested to state if a complete steel deck is fitted.

note:- Date of Build 1920



Lloyd's Register
 Foundation