


Steam Trawler "SAINT SIMON"

Regarding the equipment of this vessel it is observed that the marks for the 1st bower anchor and the kedge anchor are not decipherable, and no weights are given.

It is considered that the weights of these anchors should at least have been obtained, and it is submitted the Surveyors be requested to have these anchors weighed and report same for the information of the Committee.

Dr. Liv 16/11/33

[Signature]
16.11.33



© 2020

Lloyd's Register
Foundation