

straightened and replaced with suitable buttstraps

his purpose and t

Sent to Chief Surveyors 30-11-14

Received from Chief Surveyors _____

VESSEL'S NAME Steub S.S. "Caeique"

Report Phl.

No. 2669.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Damage

When due _____

Vessel to be placed in dry dock & repairs effected at New York.
a Bower anchor & 30 fms. of chain cable to be replaced on board.



Lloyd's Register
Foundation

W598-0249

Wood Vess
ett.)
onth

rtained
s remov

on range

m board)
e length

Ways