

NEW YORK  
COPY FOR LONDON OFFICE  
Lloyd's Register of Shipping.

Philadelphia, Penna.,

October 11th, 1917

S. S. "CACIQUE"

COLLISION REPAIRS

BOARD SIDE:-

foot plate to remove and replace  
to renew  
to renew  
to renew  
id 2 to renew, screw blemish "CACIQUE" over tank cross  
id 2 to renew  
id 2 to renew lying at anchor in the River Delaware, October  
frames below tank top to renew  
frames above tank top to *crop* and part renew, angles and  
bracket plates to be removed or renewed as required

STARBOARD SIDE:-

foot plate to remove and replace  
to renew  
to renew  
to renew  
to renew  
frames up to tank top to renew  
frames above tank top to fair in place  
bar to scarp between 25'0" and 25'6" marks and lower half to  
renew

STAR TANK TOP:-  
BOARD SIDE:-

stringer plate to renew  
stringer to cut, straighten and fit buttstrap  
bar to cut and part renew. Tank at repairs

STARBOARD SIDE:-

stringer plate to renew  
bar to cut and part renew  
top center plating to fair in place

FORE PEAK TANK:-

*crop*  
deck plates to *crop* and part renew  
deck beams removed and replaced  
over beams to remove and replace  
over stringer plates (on each side) to renew  
over plate on each side to fair in place  
anchion to remove and replace  
sounding pipes to overhaul  
air pipe to part renew  
all to remove, tank to clean out and test on completion of  
repairs and prove tight  
ballast tank to steam, clean out and rivets and seams in  
of tank end all to overhaul and make good



© 2020

Lloyd's Register

FW598-0263

Classification  
Register  
age 15  
with  
14  
if assigned  
and now ver  
or this pur  
name  
and  
to be  
ste  
long  
and in  
row  
er, or Y.M.  
State if  
When put  
s  
s, Yards,  
dition, how  
ate if u  
pment le  
ors, No.  
es (State  
length  
Rule le  
ser & W  
ding & R  
the Reg  
n as cl  
my  
Ed  
Bas  
yd's R

oked  
ML  
repairs