



January 19th 1917

S.S. "CACIQUE"

(2)

REPAIRS TO HEAVY WEATHER:-

Hatch coamings and main deck in way slightly set down.

Hatch coamings, lower deck, slightly set down.

REPAIRED:- The vessel being urgently required, it was arranged that temporary wood stanchions secured as directed in way of hatch coamings.

PERMANENT REPAIRS AT END OF PRESENT VOYAGE:-

Hatch coamings, main deck, to be faired and new butt strap fitted.

*No 1 hatch*

girders and tie bars in way of main deck to be faired in place.

Plating plates, No 1 hatch, lower deck, to be faired in place, and butt strap re-riveted.

Lower hold to be cleaned and painted with two coats of paint as before.

Deck relaid locally and two planks to be renewed.

Repaired work to be painted as before.

*3500/100*

*[Handwritten Signature]*

of Classification  
as in Regt  
CTER.  
Survey  
vey and of  
Surveys.  
*Shell*  
*Sub*  
*14*  
*rd (if assign*  
*ip and now*  
*es for this*  
*om ?*  
*ic to*  
*am*  
*re*  
*sho*  
*Stas*  
*ms :-*  
Copper, or Y.M.  
(State if  
When put  
Boats  
Masts, Yards,  
Condition, how  
(State if  
ails  
Equipment let  
anchors, No. o  
ables (State  
length  
(on b  
Rule len  
awser & Wa  
standing & Bu  
in the Regi  
tain as clas  
*em*  
*who*  
*d +*  
*out*  
*Ker*  
Lloyd's Reg



© 2020

Lloyd's Register Foundation

W598 0268 2/2