

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME Non-propelling Cutter Suction Dredger Rpt. Gls No. 54092  
 Wm. Simons No. 704

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey.....

This vessel, after erection, has been dismantled and shipped to Burmah for re-erection.

It is submitted action be deferred, the Rangoon Surveyor advised and requested to give the case the necessary attention and to forward to this Office a report on form 8 when the survey has been completed and to state thereon whether the inner surface of the bottom plating has been protected by cement.

*Anchorzahn*

*Rjn*

*(if built & Mch)*



© 2019

Lloyd's Register Foundation

W6-0132