

2m.11.35.

Report to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME "MOUNT ATHOS" Report Rot. No. 25836

For the CHIEF SHIP SURVEYOR and [redacted]

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor When due

It is submitted the attached sheet of scantlings showing the original scantlings of the ship (on which have been indicated the scantlings of the shell plating as required by the present Rules) and 2 copies of the drilling sheet be forwarded to the Dunkirk Surveyor as requested.

The Surveyor should be informed that his recommendations in respect to any renewal or doubling of any individual plates found to be unduly wasted, may (provided the surfaces of the plating are in good condition) take account of the thickness of shell plating required by the present Rules, as well as the original thickness.

The Surveyor should be requested to return the sheet when forwarding his report.

*[Handwritten signature]*  
29.3.38



© 2020

Lloyd's Register Foundation

W60-0078