

of the tanks examined. Also state the amount of ...
girders, and of the inner bottom plating, especially in the boiler space.

+100A1-2 38
10-3-2
2-34

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

Enclosure.
(Plan under
separate cover).

21st July, 1937.

Dear Sirs,

I duly received your letter of the 16th instant respecting the proposal to instal a second-hand boiler, ex s.s. "ROI LEOPOLD", in the s.s. "MOUNT ATHOS", and have to acquaint you that the scantlings of the boiler, as shown on the plan forwarded by you, meet the requirements of the Rules for a working pressure of 90 lb. per sq. inch, and no exception will be taken to the proposed installation, provided the boiler be examined and be found or placed in good condition, the scantlings be in accordance with the plan, and the boiler be found sound and tight under hydraulic test.

I shall be glad if you will ascertain whether it can be definitely established that this boiler was constructed under the survey of the British Corporation.

The plan is returned herewith.

I acknowledge the receipt of your telegram, decoded as follows: "Mount Athos. Referring to my letter of 16th instant, Owners pressing for reply".

I am, Dear Sirs,
Yours faithfully,



Lloyd's Register
Secretary.
W 60-0082

The Surveyors,
ROTTERDAM.

Subject to Shellplate D.3 f.s and Buttstrap just. Shellplate being sea