

1

Sent to Chief Surveyors

19. 9. 18

Received from Chief Surveyors

VESSEL'S NAME

Shells Machanda

Report

Sub

No. 17350

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 34/5/82.)

Nature of Survey

When due

The donkey pump & Kedge anchor have been dispensed with for the present, as approved.

100A-1 (Steel)

2 Dns Steel 3 DK (Steel) in hot steel

Cell DB 456' 23236 D.T. a 39' 15036 F.P.T. 1176 A.P.T. 1206

FK Intermediate BH in lower dks dispensed with 7 BH upper dk 1 BH to 2 Dns only.

Can Legos as per P 52 B 157 F 40. Carrying oil fuel 150 F.P.T. DB & D.T.

The Certificate of Classification, to be endorsed

"Cargo battens not fitted" and the same

notation to be printed in the Register Book.

W600-0147

