

COPY.

Hamburg Report No. 21236

# Lloyd's Register of Shipping.

Port of H A M B U R G .

24th July, 1934.

This is to Certify that I have

Surveyed the Boiler and Machinery of the Steel Twin Sc. Sr.

RUY BARBOSA " 9791 tons gross of Rio de Janeiro  
float and in dry dock at Hamburg, for the requirements of  
Completion Boiler Survey, Limitation Survey and Exam. of Tail Shafts  
and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all  
recommendations made by me in connection therewith have  
been carried out to my satisfaction, and that I have

Recommended that the record of B.S. - 6,34, T.S. (00)

be made in the Register Book in the case of this vessel, subject  
starboard main Engine MP cylinder be re-examined within  
months, say before January, 1935.

Friedrich H. H.

Engineer Surveyor to Lloyd's Register

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is  
understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for  
accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other  
publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents  
of the Society."

10m.11.29.

Lloyd's Register  
W602-70006  
Foundation

al Damage or Repair Fee (if any)..... £ :  
(per Section 29.)

Received by me,