

Class to Subject to Star main engine M.P. Cylinder being
examined before end of 12.34.

11-1 AUG 1934

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

Ruy Barbosa

Rpt.

Star

No. 21236

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey

COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 4.34 ~~now~~ partly held 6.34 now

completed, and the following repairs carried out (due to ~~non-attendance~~):-

Star boiler furnace repaired & placed in order
Star M.P. Cylinder examined when previously repaired & in the
Surveyor's opinion efficient but should be re-examined before
7.1.35

It is submitted the vessel is eligible to remain as classed, with
notation of B.S. 6.34 S. 7.34 Subject as recommended.

© 2019

Lloyd's Register
Foundation

7000-2099M